

B&G report to business meeting Jan. , 2016

1. Next work day in Feb. 27, 2016. Repair handicap ramp rotten wood, lots of indoor work, kitchen painting.
2. Bailey Roofing quotes for cement or cap roof peak. Chimney flashing may need attention.
3. De-humidifier in basement always needs to be emptied; if you are here, check it.
4. Gas leak follow up – no problem found. We relit pilot lights.

Next meeting: Feb. 7, 2016?